L Number			DB	Time stamp
-	335	73/818.ccls.	USPAT;	2003/10/29 14:2
	ı		US-PGPUB:	2003/10/29 14:2
				·
			ЕРО; ЛРО;	
			DERWENT;	. [
_	20244	((lead wire cable strand) noor ()104	IBM_TDB	
]	((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/07 15:5
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	US-PGPUB;	
	Ì	weld\$4 fix\$4 secur\$4))	ЕРО; ЛРО;	
			DERWENT;	
	ļ			
-	16023	(((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	IBM_TDB	1
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	USPAT;	2003/04/07 15:4
		Weld\$4 fix\$4 secur\$4))) and (housing cos\$4 had	US-PGPUB;	1
		weld\$4 fix\$4 secur\$4))) and (housing cas\$4 body packag\$4 structure mount\$4 backing assembl\$4)	ЕРО; ЛРО;	
		mounts4 backing assembl\$4)	DERWENT;	
	0003		IBM_TDB	
-	8993	(((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/07 15:4
		Observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4		2003/04/07 13:4
		weld\$4 fix\$4 secur\$4))) same (housing cas\$4 body packag\$4 structure	US-PGPUB;	
		mount\$4 backing assembl\$4)	ЕРО; ЈРО;	
		ozornie nosciiona)	DERWENT;	
_	15971	(((load prime calls start))	IBM_TDB	
	1/861	(((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/07 15:5
		observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	US-PGPUB;	3555,64,01,13.3
		weld\$4 fix\$4 secur\$4))) and (housing case casing body packag\$4	ЕРО; ЛРО;	
		structure mount\$4 backing assembl\$4)		1
ļ			DERWENT;	
. [375	((((lead wire cable strand) noor6 (m)))\$4	IBM_TDB	
1		((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/07 15:50
	1	observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	US-PGPUB;	
,	ł	weid\$4 fix\$4 secur\$4))) same (housing cas\$4 body packag\$4 structure	ЕРО; ЛРО;	
		mount\$4 backing assembl\$4)) and 73/\$6.ccls.	DERWENT;	ľ
İ	ļ		IBM_TDB	
	719	((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4		2002/04/07 45 55
	1	observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	USPAT;	2003/04/07 15:50
	1	weld\$4 fix\$4 secur\$4))) and (housing case casing body packag\$4	US-PGPUB;	l
1		structure mount\$4 backing assembl\$4)) and 73/\$6.ccls.	ЕРО; ЈРО;	
1	ĺ	su detaile mounts4 backing assembly4)) and /3/\$6.ccls.	DERWENT;	
,	77	///// 1 ' 11 · · · · · · · · · · · · · · · ·	IBM_TDB	
]		((((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/08 14:34
[observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	US-PGPUB;	2003/01/00 14:54
1		weld\$4 I1x\$4 secur\$4))) same (housing cas\$4 hody packag\$4 structure	ЕРО; ЛРО;	
1	1	mount\$4 backing assembl\$4)) and 73/\$6.ccls.) and ceramic		
		o	DERWENT;	
1	144	((((()lead wire cable strand) noor6 (m)11841 84 8	IBM_TDB	
	• • • • • • • • • • • • • • • • • • • •	(((((lead wire cable strand) near6 (pull\$4 push\$4 test\$4 monitor\$4	USPAT;	2003/04/08 16:20
	1 '	observ\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	US-PGPUB,	
	'	weld 11x 4 secur 4)) and (housing case casing body packag 4	ЕРО; ЛРО;	
] :	structure mount\$4 backing assembl\$4)) and 73/\$6.ccls.) and ceramic	DERWENT;	
			IBM TDB	
	0 0	(((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4		2002/04/22
	1 6	detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 weld\$4 fix\$4	USPAT;	2003/04/08 17:28
	1.	secur\$4) near6 (null\$4 nugh\$4))) ages 4	US-PGPUB;	
		secur\$4) near6 (pull\$4 push\$4))) same (housing cas\$4 body packag\$4	ЕРО; ЛРО;	
	1	structure mount\$4 backing assembl\$4) same ceramic)) and 73/\$6.ccls.	DERWENT,	
			IBM_TDB	
	2 (((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	USPAT;	2003/04/08 15:04
	0	ielect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 weld\$4 fiv\$4	US-PGPUB;	2003/04/08 13:04
	l s	secur\$4) near6 (pull\$4 push\$4))) same (housing casse casing body		
	l n	packag\$4 structure mount\$4 backing assembl\$4) same ceramic))	ЕРО; ЈРО;	
	"	odening assemble ()	DERWENT;	
	6 6	((((lead wire eable street))	IBM_TDB	
	0 1 (((((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	USPAT;	2003/04/08 16:46
	l a	letect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	US-PGPUB;	
	10	esist34 weld34 fix34 secur\$4) near6 (pull\$4 push\$4))) same (housing	EPO; JPO;	
	c	asse casing body packag\$4 structure mount\$4 backing assembl\$4)	DEDUZENE.	
	l s	ame ceramic))	DERWENT;	
			IBM_TDB	

	3:	3 ((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4		
		detect\$4 determin\$4) near4 (adhea\$4 athaa\$4)	USPAT;	2003/04/08 16:0
	ł	detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	US-PGPUB	;
	ł	resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 tesnion\$4 break\$4	ЕРО; ЛРО;	
		push\$4)) and ((ceramic) near4 (housing case casing body packag\$4	DERWENT	:
	130	structure mount\$4 backing assembl\$4))	IBM TDB	'
-	130	1 (Command of the state of the	USPAT;	2003/04/08 16:1
		detects4 determins4) near4 (adhess4 adhers4 joins4 force strength	US-PGPUB:	2003/04/08 10:1
	1	resistad weldad fixad secural) near6 (pullad tensionad breakad		'
	İ	push\$4)) and 73/\$6.ccls.	ЕРО; ЛРО;	
	1	"	DERWENT;	
-	35	((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	IBM_TDB	
		detect\$4 determin\$4) near4 (hand\$4) near6 (multiple and sensite	USPAT;	2003/04/08 16:2
		detect\$4 determin\$4) near4 (bond\$4) near6 (pull\$4 tension\$4 break\$4 push\$4)) and 73/\$6.ccls.	US-PGPUB;	
		Pastro 1)/ mid 75/\$0.0015.	ЕРО; ЛРО;	
			DERWENT;	
	150	uun 1 : 11	IBM_TDB	
-	150	1 CONTRACTOR STATE OF THE PROPERTY OF THE PROP	USPAT;	2003/04/08 16:29
•	Í	observ\$4 sens\$4 detect\$4 determin\$4) near4 (bond\$4))) and (bousing	US-PGPUB;	2003/04/08 10.2
	ľ	case casing body packag\$4 structure mount\$4 backing assembl\$4)) and	EPO; JPO;	
		73/\$6.ccls.) and ceramic		
			DERWENT;	
-	0	((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	IBM_TDB	
		detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	USPAT;	2003/04/08 16:53
		resist\$4 weld\$4 fiv\$4 cour\$4) ==== (==1154 join\$4 force strength	US-PGPUB;	
		resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 push\$4)) same (clamp\$4 grip\$4) same ceramic	ЕРО; ЛРО;	
	ĺ	gripo4) same ceramic	DERWENT;	
	1 .		IBM_TDB	
-	0	1 (1-1-1 11-1 days stated) ficato (testar filofillo) ar observad cencia	USPĀT;	2003/04/08 17:01
	ļ	detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	US-PGPUB;	2003/01/00 17:01
		bond\$4 resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 push\$4)) same	ЕРО; ЛРО;	
	ł	(clamp\$4 grip\$4) same ceramic	DERWENT;	
-	74	((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	IBM_TDB	200241040
	1	detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4 force strength	USPAT;	2003/10/29 13:10
	İ	bond\$4 resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4 push\$4)) same	US-PGPUB;	
		(clamp\$4 grip\$4)	ЕРО; ЛРО;	
	1	(Claimpor gripor)	DERWENT;	
_	209	73/827.ccls.	IBM_TDB	
	209	1/3/82/.CCIS.	USPAT;	2003/10/29 14:29
			US-PGPUB;	
			ЕРО; ЛРО;	
	1		DERWENT;	
			IBM_TDB	Ť.
· [81	73/830.ccls.	USPAT;	2002/10/20 14 20
	1			2003/10/29 14:29
			US-PGPUB;	
			ЕРО; ЛРО;	
] [DERWENT;	
	122	73/834.ccls.	IBM_TDB	
İ	122	73/034.0015.	USPAT;	2003/10/29 14:29
			US-PGPUB;	
	ļj		ЕРО; ЛРО;	
	l i		DERWENT,	
ĺ			IBM_TDB	
İ	3573	((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	USPAT;	2002/04/00 17.52
	1	detect\$4 determin\$4) near6 (pull\$4 push\$4))	US-PGPUB;	2003/04/09 17:52
	ı	, (f f		
			ЕРО; ЈРО;	
			DERWENT;	
	31	(73/827 colo 73/920 colo 73/924)	IBM_TDB	
	31	(73/827.ccls. 73/830.ccls. 73/834.ccls.) and ((lead wire cable strand)	USPAT;	2003/04/08 17:33
		nearo (test\$4 monitor\$4 observ\$4 sens\$4 detect\$4 determin\$4) nearo	US-PGPUB;	
	i i	(pull\$4 push\$4))		
		1	EPO: JPO:	
			EPO; JPO; DERWENT;	

-	103	((lead wire cable strand) near (torted)		
		((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 sens\$4	USPAT;	2003/04/09 17:5
	}	detect\$4 determin\$4) near6 (pull\$4 push\$4)) and (bolt\$4 near8 nut)	US-PGPUB	;
	1		ЕРО; ЛРО;	
	1		DERWENT	.
_	1 ,,,		IBM_TDB	'
-	111	((lead wire cable bond\$4 strand) near6 (test\$4 monitor\$4 observ\$4	USPAT;	2003/04/09 17:5
		sensor detects determins near (pulls push 4)) and (bolt a near 8	US-PGPUB;	2003/04/09 17.3
		nut)	ЕРО; ЛРО;	
	1		DERWENT;	
	1		IBM TDB	
-	10	("5085084" "6230569" "4677370" "5753823" "5836071").pn.		20021041024
	•	э этобода эбоботт у.рп.	USPAT;	2003/04/09 19:40
			US-PGPUB;	
			ЕРО; ЈРО;	
	!		DERWENT;	
-	5	("5085084" "6230560" "4627270" "5772200" "577	IBM_TDB	
-	361	("5085084" "6230569" "4677370" "5753823" "5836071").pn.	USPAT	2003/04/09 19:40
	501	((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 asses\$4	USPAT;	2003/10/29 14:21
		measur\$4 meter\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4	US-PGPUB;	2005/10/25 14.2
		Julia force strength bonds4 resists4 welds4 fix\$4 secur\$4) near	ЕРО; ЛРО;	
		(Pull 34 push 34 force load \$4)) and ((clamp \$4 hold \$4 secur \$4 grin \$4)	DERWENT;	
		near4 (base package board substrate))	IBM TDB	
3	15	(((lead wire cable strand) near6 (test\$4 monitor\$4 observ\$4 asses\$4		2002/10/20 20 20 20
	1	measury4 metery4 sensy4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4	USPAT;	2003/10/29 14:22
		join\$4 force strength bond\$4 resist\$4 weld\$4 fix\$4 secur\$4) near6	US-PGPUB;	1
	i	(pull\$4 push\$4 force load\$4)) and ((clamp\$4 hold\$4 secur\$4 grip\$4)	ЕРО; ЛРО;	
	ļ	near4 (base package board substrate))) and braz\$4	DERWENT;	
	346	73/818.ccls.	IBM_TDB	
			USPAT;	2003/10/29 14:37
	ļ		US-PGPUB;	
			ЕРО; ЛРО;	
ļ	1		DERWENT;	
j	216	73/937	IBM_TDB	
j	210	73/827.ccls.	USPAT;	2003/10/29 14:29
İ	İ		US-PGPUB;	2003/10/27 14.29
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
1	83	73/830.ccls.	USPAT;	2002/10/20 * * * *
				2003/10/29 14:29
1	1		US-PGPUB;	
			EPO; JPO;	•
			DERWENT;	ŀ
	123	73/834.ccls.	IBM_TDB	
			USPAT;	2003/10/29 14:29
			US-PGPUB;	
			ЕРО; ЛРО;	
		1	DERWENT;	
	,,	72/010 1 72/027 1 72/0	IBM_TDB	
	13 (73/818.ccls. 73/827.ccls. 73/830.ccls. 73/834.ccls.) and (((lead wire	USPAT;	2003/10/29 14:38
	10	able strand) nearb (test\$4 monitor\$4 observ\$4 asses\$4 measur\$4	US-PGPUB;	2003/10/29 14:38
	I	neter\$4 sens\$4 detect\$4 determin\$4) near4 (adhes\$4 adher\$4 join\$4	EPO; JPO;	İ
	1.6	orce strength bond\$4 resist\$4 weld\$4 fix\$4 secur\$4) near6 (pull\$4		
[1	The state of the s	DEDITION	
	p p	oush\$4 force load\$4)) and ((clamp\$4 hold\$4 secur\$4 grip\$4) near4	DERWENT; IBM_TDB	